

Property Address:	123 FAKE STREET FAKETOWN, CA 98765
Inspection Date:	06/24/2013 2:05 PM
Inspection Type:	Periodic
Inspected By:	Brandan Nordell



## Comments:

Needs Repair:	Family Room - Ceiling / Walls	2
	Kitchen / Breakfast - Dishwasher	3
	Bathroom #1 - Toilet / Lid / Seat / Paper	
	Holder	5
	Safety - Carbon Monoxide Detectors	7

Entry	Status	Comments
Door Locks / Knobs	Fair	Paint chipping around handle
Lights / Ceiling Fans	Good	
Ceiling / Walls	Good	
Flooring	Fair	Chipped tile in entry way
Living Room	Status	Comments
Lights / Ceiling Fans	Good	
Ceiling / Walls	Good	Living room wall painted red



Windows / Screens	Good
Window Latches	Good
Drapes / Blinds / Shutters	Good
Plugs / Switches	Good
Flooring	Good
Fireplace	Good



Other

Good

Family Room	Status	Comments	
Ceiling / Walls	Needs Repair	Water leak has damaged ceiling.	
Windows / Screens	Good	Blinds look good	
Window Latches	Good		
Drapes / Blinds / Shutters	Good		
Plugs / Switches	Good		
Lights / Ceiling Fans	Good		
Flooring	Good		

## Inspection Detail Report #250 for 123 FAKE STREET - 06/24/2013

-

Kitchen / Breakfast	Status	Comments	
Blinds	n/a		
Windows	n/a		
Plugs	n/a		
Door	n/a		
Floor	n/a		
Ceiling	n/a		
ights	n/a		
Formal Dining Area	Status	Comments	
Dther	Good		
Fireplace	Good		

Page 3 of 8

Flooring



Drawers / Handles	Good	
Range / Cook Top	Good	
Microwave	Good	
Dishwasher	Needs Repair	Dishwasher is leaking
Oven - Racks / Knobs	Good	
Oven - Broiler / Pan	Good	
Oven - Light Cover / Bulb	Good	
Vent Hood - Light / Fan	Good	
Vent Hood - Filter	Good	
Garbage Disposal	Good	
Ceiling / Walls	Good	
Plugs / Switches	Good	
Refrigerator	Good	
Sink / Faucets	Good	
Windows / Coverings	Good	
Doors	Good	
Countertops	Good	
Lights	Good	





Pantry	Good		
Hallway	Status	Comments	
Lights / Ceiling Fans	n/a		
Ceiling / Walls	Good		
Plugs / Switches	Good		
Flooring	Good		
Closet	n/a		
Cabinets	n/a		

Lights / Ceiling Fans     Good       Ceiling / Walls     Good	Bedroom #1	Status	Comments
Ceiling / Walls Good	Lights / Ceiling Fans	Good	
	Ceiling / Walls	Good	



Windows / Screens	Good
Window Latches	Good
Drapes / Blinds / Shutters	Good
Plugs / Switches	Good
Flooring	Good
Doors / Door Stops	Good
Closet	Good
Other	n/a

Bedroom #2	Status	Comments
Lights / Ceiling Fans	Good	
Ceiling / Walls	Good	
Windows / Screens	Good	
Window Latches	Good	
Drapes / Blinds / Shutters	Good	
Plugs / Switches	Good	
Flooring	Good	
Doors / Door Stops	Good	
Closet	Good	
Other	n/a	
Bedroom #3	Status	Comments
Lights / Ceiling Fans	Good	
Ceiling / Walls	Fair	Hole in wall





Windows / Screens	Good	
Window Latches	Good	
Drapes / Blinds / Shutters	Good	
Plugs / Switches	Good	
Flooring	Good	
Doors / Door Stops	Good	
Closet	Good	
Other	n/a	
Bathroom #1	Status	Comments
Lights / Ceiling Fans	Good	
Plugs / Switches	Good	
Closet Shelves / Rods	Good	

Good

Good

## Sinks / Faucets Good Tub / Shower / Faucets Good Toilet / Lid / Seat / Paper Holder Needs Repair

Cabinets / Handles

Counter Tops

Toilet is leaking



Heaters / Exhaust Fans	Good
Towel Fixtures	Good
Doors / Door Stops	Good
Flooring	Good
Ceiling / Walls	Good



Windows	n/a
Other	n/a

Bathroom #2	Status	Comments
Lights / Ceiling Fans	Good	
Plugs / Switches	Good	
Closet Shelves / Rods	Good	
Cabinets / Handles	Good	
Counter Tops	Good	
Sinks / Faucets	Good	
Tub / Shower / Faucets	Good	
Toilet / Lid / Seat / Paper Holder	Good	
Heaters / Exhaust Fans	Good	
Towel Fixtures	Good	
Doors / Door Stops	Good	
Flooring	Good	
Ceiling / Walls	Good	
Windows	Good	
Other	n/a	
Laundry Room	Status	Comments
Walls/Ceilings	Good	Very clean



Lights/Switches/Outlets	Good	
Flooring	Good	
Washer	Good	
Dryer	Good	
Windows/Blinds/Screens	Good	No blinds
Vent Fan	Good	
Sink/Washtub	Good	
Other	n/a	
Door(s)	Good	
Safety	Status	Comments
HVAC Filter	Good	Changed filter
Smoke Detectors	Good	
Carbon Monoxide Detectors	Needs Repair	Needs CO detectors installed - 1 per floor
Garage	Status	Comments
Garage Door	Fair	Squeaky when going up. Door is dented along the bottom.
Garage Door	Fair	
Garage Door	Fair	
Garage Door	Fair Good Good	
Garage DoorImage DoorImage Exterior DoorWater HeaterInterior	Fair A Good Good	
Garage Door         Image Door         Garage Door         Garage Exterior Door         Water Heater         Interior         Flooring	Fair Good Good Good	
Garage DoorImage DoorImage DoorGarage Exterior DoorWater HeaterInteriorFlooringOther	Fair Good Good Good Good	Squeaky when going up. Door is dented along the bottom.
Garage Door     Image Diage     Garage Exterior Door   Water Heater   Interior   Flooring   Other	Fair Good Good Good Good Good n/a <b>Status</b>	Squeaky when going up. Door is dented along the bottom.
Garage Door     Image Exterior Door   Water Heater   Interior   Flooring   Other   Other	Fair A A A A A A A A A A A A A A A A A A A	Squeaky when going up. Door is dented along the bottom.
Garage DoorImage DoorImage DoorGarage Exterior DoorWater HeaterInteriorFlooringOtherOtherOther 1Other 1Other 2	Fair	Squeaky when going up. Door is dented along the bottom.
Garage DoorImage Exterior DoorGarage Exterior DoorWater HeaterInteriorFlooringOtherOtherOther 1Other 1Other 2Other 3	Fair         Image: Constraint of the second state of the second stat	Squeaky when going up. Door is dented along the bottom.

Exterior	Status	Comments
Driveway	Good	
Porch	Good	
Lawn	Good	Looks good
Shrubbery	Good	
Exterior Walls	Good	
Roof / Gutters	Good	
Fence / Gates	Good	Fence is leaning in backyard by bushes
Sprinklers / Irrigation	Good	
Other	n/a	